



Test Report

Report No.: HLF1402072E

Report Date: 2014-2-26

Page: 1 of 4

Company Name :

Address :

The following sample information was Submitted and Identified by the Client:

Sample Name : running blet with pouches

Sample model : NK0001

Sample Lot : /

Receiving Date : 2014-2-20

Complete Date : 2014-2-26

Test Requested : As specified by client, Determine the content of Phthalates in the submitted sample

Test Method : Refer to EN14372(2004)

Test Results : Please refer to next page

Prepared by:

Cathy

Report Clerk

Checked by:

Mary

Lab Senior Engineer

Approved by:

Eric

Lab Supervisor

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.



FLION TESTING SERVICE

Add: Mangzi Industrial Park, Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City

Tel: 86-0755-2724 8885 Fax: 86-0755-2746 0090 Http://www.sz-fts.com

Test Report

Report No.: HLF1402072E

Report Date: 2014-2-26

Page: 2 of 4

Test Result:

Test Item	Test Method / Instrument	Unit	MDL	Result	Limit
Dibutyl phthalate (DBP)	EN14372(2004)/GC-MS	%	0.005	N.D.	0.1
Butyl benzyl phthalate (BBP)	EN14372(2004)/GC-MS	%	0.005	N.D.	0.1
Bis-(2-ethylhexyl)phthalate (DEHP)	EN14372(2004)/GC-MS	%	0.005	N.D.	0.1
Di-n-octyl phthalate(DNOP)	EN14372(2004)/GC-MS	%	0.005	N.D.	0.1
Di-isodecyl phthalate(DIDP)	EN14372(2004)/GC-MS	%	0.01	N.D.	0.1
Di-isononyl phthalate(DINP)	EN14372(2004)/GC-MS	%	0.01	N.D.	0.1

- Note:
- 1.1ppm= 1mg/kg=0.0001%;
 - 2.N.D.=Not Detected(<MDL);
 - 3.MDL= Method Detection Limit;
 - 4.“--”=Not Regulated;

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.



FLION TESTING SERVICE

Add:Gangzi Industrial Park, Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City

Tel: 86-0755-2724 8885 Fax:86-0755-2746 0090 Http://www.sz-fts.com


Test Report

Report No.: HLF1402072E


Report Date: 2014-2-26

Page: 3 of 4

Testing Flow Chart:



In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.



FLION TESTING SERVICE

Add: Gangzi Industrial Park, Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City

Tel: 86-0755-2724 8885

Fax: 86-0755-2746 0090

Http://www.sz-fts.com

Test Report

Report No.: HLF1402072E

Report Date: 2014-2-26

Page: 4 of 4

Sample Description: running belt with pouches

Sample photo:



(Remark: According to client's requirement, the submitted samples were mixed to perform the test)

Note: The results show in this report is only responsible for the sample. The test report shall not be reproduced except in full, without written approval of the laboratory.

***** End of the report *****

In no circumstances shall the Company's responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected, tested and surveyed by the Company and any inference to be drawn from the results of such inspection or survey or testing shall be entirely in the discretion and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.



FLION TESTING SERVICE

Add: Gangzi Industrial Park, Furong Industrial Area, Xinqiao Village, Shajing Town, Bao'an District, Shenzhen City

Tel: 86-0755-2724 8885 Fax: 86-0755-2746 0090 Http://www.sz-fts.com